



Irbit MotorWorks of America, Inc.

14700 NE 95-th Street, Suite 102, Redmond, WA 98052 Ph: 425.702.8484

Fax: 425.696.0834 info@imz-ural.com

IMPORTANT SAFETY RECALL-NHTSA Recall No. 13V-507

This notice applies to your vehicle: [Insert VIN here]

Dear Ural motorcycle owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Reason For This Recall

Irbit Motorworks has decided that a defect which relates to motor vehicle safety, exists in certain model year 2012 Ural Gear-up, Patrol, Patrol T, Tourist, and Tourist T motorcycles with sidecars produced June 2, 2012 through October 25, 2012. It was found that aluminum rims stamped with a manufactured date of April 2012 may be defective. This defect may result in cracks, damaged rims and/or motor vehicle crash.

What We Will Do

All affected motorcycles will be inspected for this defect: if it is found your motorcycle is equipped with aluminum rims stamped with a manufactured date of April 2012 they will be replaced at no charge to you.

What You Should Do

Please contact your nearest Ural dealer and/or repair facility as soon as possible to schedule a service appointment. You may be asked to provide your VIN (vehicle identification number) for confirmation of recall. The labor time for this repair can vary and you may be asked by your dealer to leave the motorcycle for the repair.

Your Ural dealer is best equipped to obtain parts and provide service to ensure that your vehicle is corrected as promptly as possible. If, however, you take your vehicle to your dealer on the agreed service date, and they do not remedy this condition on that date or within three (3) days, we recommend you contact Ural customer service by calling 1-800-520-0534.

After contacting your dealer and Ural customer service, if you are still not able to have the safety defect remedied without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E. , Washington, DC 20590 or call 1-888-327-4236 (TTY: 1-800-424-9153) or go to <http://www.safercar.gov>.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Ural Customer Service at 1-800-520-0534. If you have sold or traded your vehicle, please let us know by calling Ural Customer Service at 1-800-520-0534.

Federal Law requires any lessor who receives a notification of determination of a safety related defect or noncompliance pertaining to any leased motor vehicle shall send the notice to the lessee within 10 days.

We are sorry to cause this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

Sincerely,
Irbis Motorworks of America, Inc